

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

EG660
NE
1/2-1
0.960 mi.
5068 ft.

VS6462
AVENUE X EAST 3RD STREET
BROOKLYN, NY

NY Spills S105140755
N/A

Site 1 of 2 in cluster EG

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: VS6462
Address: AVENUE X EAST 3RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0104076 / 2001-08-23
Facility ID: 0104076
Facility Type: ER
DER Facility ID: 199768
Site ID: 243188
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2001-07-17
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2001-07-17
CID: 207

Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-07-17
Spill Record Last Update: 2001-08-31
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: CHARLIE MCCARTHY
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL CON ED E2MIS REPORT 7-17-01 1/2 pt. unknownoil on 2gals.water found in earthen sump pit in VS 6462. Found after a flush crew flushed the MH. They notice doil coming form under the transformer. The truck is now contaminated and will sit in the yard pending results of sample taken from structure. Pressure tested unit and it passed. Historical records indicate <10ppm unit dated 1986. No sewer connection. 1400hrs. Truck is quarantined until results of sample have been had. Sump samples were also taken and the sump cemented and structure cleaned by double washing with slix. Tag removed. "

Remarks: "1/2 pint total on 2 gals water samples taken - cleanup pending results con ed 138287"

All Materials:

Site ID: 243188
Operable Unit ID: 842598
Operable Unit: 01
Material ID: 560316
Material Code: 0066A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported